

Rust Removal – Tool Restoration

One part linseed oil
One part white vinegar
One part mineral turps

Rust Bust

A container which will take all the parts and odds and ends (ie lathe bed etc)

From a farm supplier purchase some Molasses

The recipe requires 20 parts of water to 1 part Molasses

All parts need to immersed completely and left for about 2 to 3 weeks

Take and power wash

You will find the castings will be as if just cast and any parts that were seized up will be free.

You can then spray or brush on paints.